

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
1-DOV.V,
1-A-

John Dickinson Feed Barn (Reconstruction)
Kitts Hummock Road
Dover Vicinity
Kent County
Delaware

HABS No. DE-17-A

Photographer: David Ames

September 1985

DE-17-A-1	VIEW NORTHWEST, JOHN DICKINSON MANSION AND FEED BARN
DE-17-A-2	VIEW NORTHWEST, SOUTH AND EAST ELEVATIONS
DE-17-A-3	VIEW WEST, EAST ELEVATION
DE-17-A-4	VIEW WEST, EAST ELEVATION DETAIL
DE-17-A-5	VIEW SOUTH, NORTH ELEVATION
DE-17-A-6	VIEW SOUTHEAST, NORTH AND WEST ELEVATIONS
DE-17-A-7	VIEW EAST, WEST ELEVATION
DE-17-A-8	VIEW NORTHEAST, WEST AND SOUTH ELEVATIONS
DE-17-A-9	VIEW NORTH, SOUTH ELEVATION
DE-17-A-10	DETAIL OF JOISTS DROP MORTICED INTO SILLS OVER WALNUT BLOCKS
DE-17-A-11	DETAIL OF NORTHWEST CORNER
DE-17-A-12	DETAIL OF INTERIOR LOOKING SOUTHEAST